Aurecon New Zealand Limited T +64 3 366 0821 (PO Box 1061) Christchurch 8140 New Zealand

Unit 1, 150 Cavendish Road F +64 3 379 6955
Casebrook F +64 3 379 6955
E christchurch@ap.aurecongroup.com W aurecongroup.com



26 March 2014

Fulton Hogan Land Development Ltd 29 Sir William Pickering Drive PO Box 39185 Christchurch 8545 Attn: Greg Dewe

Dear Greg,

FULTON HOGAN LAND DEVELOPMENT LIMITED STAGE 4 ROSEMERRYN FARM SUBDIVISION **GEOTECHNICAL COMPLETION LETTER REPORT – RESOURCE CONSENT 135618** Our Ref: 224464

This geotechnical completion letter report is submitted in accordance with Section 12.4.1 of the Selwyn District Council Engineering Code of Practise.

1. Introduction

As part of the Fulton Hogan Land Development Limited (FHLD) Rosemerryn Subdivision Development located at Lincoln, Aurecon has undertaken a geotechnical investigation and assessment for Stages 3 to 6. This is detailed in the Aurecon geotechnical report "Geotechnical Assessment Report Revision 3, Rosemerryn Farm Stages 3 to 6, Fulton Hogan Land Development Limited", dated 3 May 2012.

The report was issued following the publication of the Ministry of Business Innovation & Employment (MBIE) formerly the Department of Building and Housing, guidelines in November 2011, which define the new Technical Category zoning and the liquefaction induced deformation limits for each Technical Category.

The categories and corresponding criteria are summarised as follows:

- Technical Category 1 (TC1) Future land damage from liquefaction is unlikely, and ground settlements are expected to be within normally accepted tolerances.
- Technical Category 2 (TC2) Minor to moderate land damage from liquefaction is possible in future large earthquakes.
- Technical Category 3 (TC3) Moderate to significant land damage from liquefaction is possible in future large earthquakes.

For the Canterbury region, the MBIE has released a new classification system for residential 'Green Zone' land on the flat in regard to liquefaction susceptibility. These are summarised below:

Table 1: Liquefaction Deformation Limits and House Foundation Implications

Technical Category	Liquefaction Deformation Limits				Likely Implication for House
	Vertical		Lateral Spread		Foundations (subject to
	SLS	ULS	SLS	ULS	individual assessment)
TC1	15mm	25mm	Nil	Nil	Standard NZS3604 type foundations with tied slabs
TC2	50mm	100mm	50mm	100mm	Enhanced foundation solutions
TC3	>50mm	>100mm	>50mm	>100mm	Site specific foundation solution



2. Liquefaction Analysis and Results

The liquefaction analysis for Stage 4 was based on the CPT testing carried out as part of the geotechnical investigations for the larger subdivision. The geotechnical investigation information used to assess Stage 4 is part of a large group of geotechnical information and only the tests that are relevant for this stage has been assessed. Consideration was given to information and data from outside the stage boundary when assessing geotechnical hazards and issues.

Based on the liquefaction and lateral spreading results, we consider Stage 4 falls within the liquefaction deformation limits of Technical Category TC2.



Figure 1: Stage 4 Rosemerryn Subdivision

Taken from Davie Lovell Smith Staging Plan for Rosemerryn Subdivision, Drawing No. E. 17975.S09 Rev2 Dated Sep 2013



Table 2: Inferred Technical Category of Lots within Stage 4

LOT	Technical Category (Based on calculated liquefaction deformation limits)	LOT	Technical Category (Based on liquefaction deformation limits)
330	TC2	343	TC2
331	TC2	344	TC2
332	TC2	345	TC2
333	TC2	346	TC2
334	TC2	347	TC2
335	TC2	348	TC2
336	TC2	351	TC2
337	TC2	352	TC2
338	TC2	353	TC2
339	TC2	354	TC2
340	TC2	355	TC2
341	TC2	356	TC2
342	TC2		

For Technical Category TC2, MBIE has recommended foundation systems for residential houses in their publication '*Repairing and rebuilding houses affected by the Canterbury earthquakes*' dated December 2012. Schematics and typical cross sections of these foundation systems are presented in the MBIE publication.

These are discussed in depth in our geotechnical investigation report.

As required under the new MBIE guidelines for detailed house design, a site specific shallow geotechnical assessment shall be carried out by a suitability qualified chartered engineer with experience in residential house development.

3. Limitations

The contents of this letter are for the sole use of the Client and no responsibility or liability will be accepted to any third party. Information or opinions contained within this letter may not be used in other contexts or for any other purposes without our prior agreement. The comments in this letter are based on our investigations of the site for the sole purposes of the geotechnical aspects only, as requested by the Client. Only a finite amount of information has been collected and this letter does not purport to completely describe all the site characteristics and properties. The extent of our investigations and the results of all the tests carried out are as described in the geotechnical report for Stages 3 to 6 "Geotechnical Assessment Report Revision 3, Rosemerryn Farm Stages 3 to 6, Fulton Hogan Land Development Limited", dated 3 May 2012.



We trust this meets your requirements and if there are any further queries please do not hesitate to contact us.

Yours sincerely

P.B. tll

Robert Smith

Geotechnical Engineer

Dr Jan Kupec

Technical Director

Attached - SDC Approved Subdivision Plan for Rosemerryn Subdivision

